


## STRUCTURAL SAFETY INSPECTION REPORT FORM

Inspection Firm or Individual Name: Property Consulting Group, Inc.Address: 405 S Federal Highway, Suite 300, Pompano Beach, FL 33062Telephone Number: (954) 946-7763Inspection Commenced Date: 12/13/2024Inspection Completed Date: 12/13/2024
☒ No Repairs Required
 ☐ Repairs are Required as Outlined in the Attached Inspection Report

 Florida Licensed Professional:
 ☒ Engineer
 ☐ Architect
Name: Jonnatán MendezLicense Number: 76858
 Threshold Building – Certified Special Inspector
 ☒ Yes
 ☐ No


Seal

I am qualified to practice in the discipline in which I am hereby signing,

Signature: [Signature]Date: 1/13/2025

This report has been based upon the minimum inspection guidelines for building safety inspection as listed in the Broward County Board of Rules and Appeals Policy #05-05. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure based upon careful evaluation of observed conditions to the extent reasonably possible.

**1. DESCRIPTION OF STRUCTURE**a. Name on Title: Four Story Residential Condominium Apartment Building with 56 Units (Application #: 1026122)b. Street Address: Lyndhurst H, Deerfield Beach, FL 33442c. Legal Description: Lyndhurst H Condo Unit 1001 PER CDO BK/PG: 5907/1d. Owner's Name: Lyndhurst H Condominium Association, Inc.e. Owner's Mailing Address: 2101 Centrepark West Dr., Suite 110, West Palm Beach, FL 33409f. Email Address: lyndhurst.h@yahoo.comContact Number: (647) 409-1893g. Folio Number of Property on which building is located: 4842-03-DH-0010h. Building Code Occupancy Classification: Residential Group R-2i. Present Use: Residentialj. General Description: Four Story Residential Condominium Building Type of Construction: III-Bk. Square Footage: Approx. 81,600SF (Google)Number of Stories: 4

l. Is this a Threshold Building (per F.S. 553.71):

☒

Yes

☐ No

m. Special Features:

None

n. Describe any Additions to the Original Structure:

No additions to original structure observed.

o. Additional Comments:

None

**2. PRESENT CONDITION OF STRUCTURE**

a. General Alignment (Note: Good, Fair, Poor, Explain if Significant):

1. Bulging:

☒

Good

☐

Fair

☐

Poor

☐

Significant (Explain):

2. Settlement:

☒

Good

☐

Fair

☐

Poor

☐

Significant (Explain):

3. Deflections:

☒

Good

☐

Fair

☐

Poor

☐

Significant (Explain):

4. Expansion:

☒

Good

☐

Fair

☐

Poor

☐

Significant (Explain):

5. Contraction:

☒

Good

☐

Fair

☐

Poor

☐

Significant (Explain):

## b. Portion Showing Distress (Note: Beams, Columns, Structural Walls, Floor, Roofs, Other):

No beams, columns, structural walls, or floors were noted to be under visible distress upon inspection.

## c. Surface Conditions – Describe General Conditions of Finishes, (Noting Cracking, Spalling, Peeling, Signs of Moisture Penetration, and Strains):

Surfaces are in good overall condition, consisting of decorative stucco with a painted finish.

## d. Cracks – Note the Location of Significant Members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1mm in width; MEDIUM if between 1mm and 2mm in width; WIDE if over 2mm:

No discernible cracks noted on significant structural members.

## e. General Extent of Deterioration – Cracking or Spalling Concrete or Masonry, Oxidation of Metals; Rot or Borer Attack in Wood:

General Condition is good. No visual cracking or spalling of concrete or masonry, oxidation of metals, rot or borer attack in wood was noted at the time of inspection and should be maintained routinely.

## f. Note Previous Patching or Repairs:

No significant previous patching or repairs were identified.

## g. Nature of Present Loading Indicate Residential, Commercial, and Other Estimated Magnitude:

A review of the prior SFBC and recent FBC indicates that the Uniform Live Load is 30 PSF for the roof and 40 PSF for the floors. The building as configured appears to meet these load requirements.

### 3. INSPECTIONS

a. Date of Notice of Required Inspection: **7/22/2024**

b. Date(s) of Actual Inspection: **12/13/2024**

## c. Name and Qualifications of the Individual Preparing Report:

James Hanskat, P.E.  
Professional Engineer, Florida Registration # 49801

## d. Description of Laboratory or Other Formal Testing, if required, rather than Manual or Visual Procedures:

Visual inspection procedures were sufficient for this Inspection.

## e. Structural Repairs:

No repairs are required

## f. Has the Property Record been Researched for any Current Code Violations or Unsafe Structure Cases?



Yes



No

## Explanation/Comments:

The City of Deerfield Beach Building Department website was reviewed and it appears that no violations or unsafe structure cases were identified that would impact the structural integrity of the building at the time of the inquiry.

**4. SUPPORTING DATA ATTACHED**

a. Sheets of Written Data: Not deemed necessary.

b. Photographs: Attached.

c. Drawings or Sketches: Not deemed necessary.

d. Test Reports: Not deemed necessary.

**5. FOUNDATION**

## a. Describe Building Foundation:

The reinforced concrete vertical structure is reinforced concrete slabs on grade (SOG) construction. The exterior walls are supported by reinforced concrete continuos footings.

b. Describe any Cracks or Separation in the Walls, Columns or Beams that Signal Differential Settlement:

No discernible cracks or separation in the walls, columns, or beams that signal differential settlement were identified.

c. Is there Additional Sub-Soil Investigation Required?

☐

Yes

☒

No

1. If yes, explain:

## 6. MASONRY BEARING WALL – Indicate Good, Fair or Poor on Appropriate Lines

a. Concrete Masonry Units:

☒

Good

☐

Fair

☐

Poor

b. Clay Tile or Cotta Units: N/A

☐

Good

☐

Fair

☐

Poor

c. Reinforced Concrete Tie Columns:

☒

Good

☐

Fair

☐

Poor

d. Reinforced Concrete Tie Beams:

☒

Good

☐

Fair

☐

Poor

e. Lintel:

☒

Good

☐

Fair

☐

Poor

f. Other Type Bond Beams: N/A

☐

Good

☐

Fair

☐

Poor

g. Masonry Finishes – Exterior:

1. Stucco:

☒

Good

☐

Fair

☐

Poor

2. Veneer: N/A

☐

Good

☐

Fair

☐

Poor

3. Paint Only:

☒

Good

☐

Fair

☐

Poor

4. Other: N/A

☐

Good

☐

Fair

☐

Poor

4a. Explain:

N/A

h. Cracks – Describe Beams, Columns, or Others, Including Locations:

No discernible cracking was noted on beams or columns.

i. Spalling – Describe Beams, Columns, or Others, Including Locations:

No discernible spalling identified on beams or columns.

j. Rebar Corrosion – Check Appropriate Line:

- |    |                                     |   |
|----|-------------------------------------|---|
| 1. | <input checked="" type="checkbox"/> | None Visible                              |
| 2. | <input type="checkbox"/>            | Minor – Patching Will Suffice             |
| 3. | <input type="checkbox"/>            | Significant – Patching Will Suffice       |
| 4. | <input type="checkbox"/>            | Significant – Structural Repairs Required |

4a. Describe:

N/A

k. Were Samples Chipped Out for Examination in Spalled Areas?

- |    |                                     |  |
|----|-------------------------------------|--|
| 1. | <input checked="" type="checkbox"/> | No   |
| 2. | <input type="checkbox"/>            | Yes – Describe Color, Texture, Aggregate, and General Quality: |

**7. FLOOR AND ROOF SYSTEM****a. Roof:****1. Describe the Type and Condition of the Current Roof:**

The low sloped flat roof is constructed of reinforced concrete and is finished with built-up roofing materials (BUR) and has a modified bitumen roof covering with silicone spray foam. Noted to be in good condition. No significant leaks were identified and any issues should be addressed as a part of routine maintenance.

**2. Note Water Tanks, Cooling Towers, Air Conditioning Equipment, Signs, Other Heavy Equipment and Condition of Support:**

Typical split system condenser units mounted on elevated metal stands. Noted to be in good condition.

**3. Note Types of Drains, Scuppers, and Condition:**

The low sloped flat roof is pitched to the roof drains and the run-off is mitigated by scuppers and downspouts. Roof drains, scuppers, downspouts and drainage were noted to be in good condition.

**4. Describe Parapet Construction and Current Condition:**

N/A

**5. Describe Mansard Construction and Current Condition:**

N/A



6. Describe any Roofing Framing Member with Obvious Overloading, Overstress, Deterioration, or Excessive Deflection:

No roof framing members were noted to show obvious overloading, overstress, deterioration or excessive deflection.

7. Note any Expansion Joint and Condition:

The building is provided with expansion joints and noted to be in good condition with no evidence of extensive movement observed.

**b. Floor System(s):**

1. Describe Type of System Framing, Material, Spans, and Condition:

The building is reinforced concrete slab on grade (SOG) construction. The floors above grade are supported by reinforced concrete. Noted to be in good condition.

2. Balconies – Indicate Location, Framing System, Material, and Condition:

The building is provided with reinforced concrete balconies located at the rear of the building. The reinforced concrete balconies were noted to be in good condition.

3. Stairs and Escalators – Indicate Location, Framing System, Material, and Condition:

Exterior reinforced concrete stairwells with concrete railings lead to the upper levels reinforced concrete catwalks with concrete railings. The reinforced stairwells are noted to be in good condition.

4. Ramps – Indicate Location, Framing System, Material, and Condition:

N/A



## 5. Guardrails – Indicate Type, Location, Material and Condition:

The building is provided with concrete railings/guradrails for the exterior stairwells and catwalks. Noted to be in good condition.

## c. Inspection:

Note: Exposed areas available for inspection and where it was found necessary to open ceilings, etc. for inspection of typical framing members.

N/A

**8. STEEL FRAMING SYSTEM**

## a. Full Description of the System:

N/A

## b. Exposed Steel – Describe the Condition of the Paint and Degree of Corrosion:

N/A

## c. Steel Connections – Describe Type and Condition:

N/A

## d. Concrete or Other Fireproofing – Describe any Cracking or Spalling and Note Where any Covering was Removed for Inspection:

No fireproofing or encased members were identified.

- e. Identify any Steel Framing Member with Obvious Overloading, Overstress, Deterioration, or Excessive Deflection. Provide Location(s):

N/A

- f. Elevator Sheave Beams, Connections, and Machine Floor Beams – Note Column:

N/A

## 9. CONCRETE FRAMING SYSTEM

- a. Full Description of the Structural System:

The exterior walls and vertical structural members of the four story building are constructed using precast concrete panels and have a painted stucco finish. The exterior walls are supported by continuous reinforced concrete footings. The buildings foundation is reinforced concrete slab on grade (SOG) construction. Framing system was noted to be in good overall condition and well maintained.

- b. Cracking:

1. ☐ Significant ☒ Not Significant

2. Description of Members Affected, Location, and Type of Cracking:

N/A

- c. General Condition:

Concrete framing was noted to be in good general condition.

## d. Rebar Corrosion – Check Appropriate Line:

- |    |                                     |  |
|----|-------------------------------------|--|
| 1. | <input checked="" type="checkbox"/> | None Visible   |
| 2. | <input type="checkbox"/>            | Location and Description of Members Affected and Type Cracking |
| 3. | <input type="checkbox"/>            | Significant – Patching Will Suffice                            |
| 4. | <input type="checkbox"/>            | Significant – Structural Repairs Required (Describe):          |

## e. Were Samples Chipped Out for Examination in Spalled Areas?

- |    |                                     |  |
|----|-------------------------------------|--|
| 1. | <input checked="" type="checkbox"/> | No   |
| 2. | <input type="checkbox"/>            | Yes – Describe Color, Texture, Aggregate, General Quality: |

N/A

## f. Identify any Concrete Framing Member with Obvious Overloading, Overstress, Deterioration, or Excessive Deflection. Provide Location(s):

No concrete framing members were noted to show obvious overloading, overstress, deterioration or excessive deflection were identified.

**10. WINDOWS, STOREFRONTS, CURTAINWALLS AND EXTERIOR DOORS**

## a. Windows, Storefronts, and Curtainwalls:

The building is provided with single hung, awning and horizontal slider windows set in aluminum frames.

## b. Structural Glazing on the Exterior Envelope of the Threshold Building:

☐

Yes

☒

No

1. Previous Inspection Date: N/A

---

## 2. Description of Curtainwall Structural Glazing and Adhesive Sealant:

N/A

## 3. Describe the Condition of System:

N/A

## c. Exterior Doors:

## 1. Type (Wood, Steel, Aluminum, Sliding Glass Door, Other):

The building is provided with wood doors with jalousie window inserts set in wood frames, wood doors set in wood frames. The patios are provided with aluminum doors with glass inserts set in aluminum frames. Noted to be in good condition.

## 2. Anchorage Type and Condition of Fasteners and Latches:

Doors attached with screws, noted to be in good condition.

## 3. Sealant Type and Condition of Sealant:

Due to design and use, sealant is not significant. Windows are sealed at sills with caulking as needed.

## 4. General Condition:

**Good**

## 5. Describe Repairs Needed:

**No repairs are needed**

**11. WOOD FRAMING**

- a. Type – Fully Describe Mill Construction, Light Construction, Major Spans, and Trusses:

N/A

- b. Indicate the Condition of the Following:

1. Walls:

Good

2. Floors:

N/A

3. Roof Member, Roof Trusses:

N/A

- c. Note Metal Fitting (i.e., Angles, Plates, Bolts, Splint Pintles, Other and Note Condition):

Plates, angles, and bolts in good condition.

- d. Joints – Note if Well Fitted and Still Closed:

Joints are well fitted and still closed.

e. Drainage – Note Accumulations of Moisture:

Drainage were noted to be in good overall condition and no accumulations of moisture were identified.

f. Ventilation – Note any Concealed Spaces not Ventilated:

N/A

g. Note any Concealed Spaces Opened for Inspection:

None

h. Identify any Wood Framing Member with Obvious Overloading, Overstress, Deterioration, or Excessive Deflection:

No wood framing members were noted to present obvious overloading, overstress, deterioration, or excessive deflection.

## 12. BUILDING FAÇADE INSPECTION (Threshold Building)

a. Identify and Describe the Exterior Walls and Appurtenances on All Sides of the Building (Cladding Type, Corbels, Precast Appliques, etc.):

The building facade is finished with a decorative painted stucco finish.

b. Identify the Attachment Type of each Appurtenance Type (Mechanically Attached or Adhered):

N/A

- c. Indicate the Condition of each Appurtenance (Distress, Settlement, Splitting, Bulging, Cracking, Loosening of Metal Anchors and Supports, Water Entry, Movement of Lintel or Shelf Angles, or Other Defects):

N/A

**13. SPECIAL OR UNUSUAL FEATURES IN THE BUILDING**

- a. Identify and Describe any Special or Unusual Features (i.e., Cable Suspended Structure, Tensile Fabric Roof, Large Sculpture, Chimney, Porte-Cochere, Retaining Wall, Seawall, etc.):

N/A

- b. Indicate the Condition of Special Feature, its Supports, and Connections:

N/A




**ELECTRICAL SAFETY INSPECTION REPORT FORM**Inspection Firm or Individual Name: Property Consulting Group, Inc.Address: 405 S Federal Highway, Suite 300, Pompano Beach, FL 33062Telephone Number: (954) 946-7763Inspection Commenced Date: 12/13/2024Inspection Completed Date: 12/13/2024☒ No Repairs Required☐ Repairs are Required as Outlined in the Attached Inspection Report

Florida Licensed Professional:

☒ Engineer☐ ArchitectName: James Hanskat, P.E.License Number: 49801

Seal

I am qualified to practice in the discipline in which I am hereby signing,

Signature: Date: 1/18/25

This report has been based upon the minimum inspection guidelines for building safety inspection as listed in the Broward County Board of Rules and Appeals Policy #05-05. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure based upon careful evaluation of observed conditions to the extent reasonably possible.

**1. DESCRIPTION OF STRUCTURE**

- |   |  |
|---|--|
| a. Name on Title:   | Four Story Residential Condominium Apartment Building with 56 Units (Application #: 1026122) |
| b. Street Address:  | Lyndhurst H, Deerfield Beach, FL 33442   |
| c. Legal Description:                                     | Lyndhurst H Condo Unit 1001 PER CDO BK/PG: 5907/1  |
| d. Owner's Name:  | Lyndhurst H Condominium Association, Inc.  |
| e. Owner's Mailing Address:                               | 2101 Centrepark West Dr., Suite 110, West Palm Beach, FL 33409                               |
| f. Email Address:   | lyndhurst.h@yahoo.com  |
| Contact Number:   | (647) 409-1893   |
| g. Folio Number of Property on which Building is Located: | 4842-03-DH-0010  |
| h. Building Code Occupancy Classification:                | Residential Group R-2  |
| i. Present Use:   | Residential  |
| j. General Description:                                   | Four Story Residential Condominium Building  |
| Type of Construction:                                     | III-B  |
| k. Square Footage:  | Approx. 81,600SF (Google)  |
| Number of Stories:  | 4  |

I. Special Features:

None

m. Additional Comments:

The building is provided with residential load centers located in the two (2) electrical rooms on the second floor of the building.

**2. INSPECTIONS**a. Date of Notice of Required Inspection: 7/22/2024b. Date(s) of Actual Inspection: 12/13/2024

c. Name and Qualifications of Individual Preparing Report:

James Hanskat, P.E.

Professional Engineer, Florida Registration # 49801

d. Are any Electrical Repairs Required?

1. ☒ No – None Required2. ☐ Yes – Required (Describe Nature of Repairs):

**\*\*\* NOTE: Provide photographs as necessary to reflect relevant conditions and index appropriately. \*\*\***

**3. ELECTRIC SERVICE**a. Size: Voltage ( 120/240 ); Amperage ( (8) 400 );b. Main Service Protection ( 8-400 Amps): ☒ Fuse ☐ Breaker

c. Service Rating Amperage ( 8-400 Amps):

d. Phase: ☐ Three Phase ☒ Single Phase

e. Condition: ☒ Good ☐ Needs Repairs

Describe the Nature of Repairs:

No repairs required.

#### 4. SERVICE EQUIPMENT

a. Clearances: ☒ Good ☐ Requires Repair

Describe the Nature of Repairs:

Clearance of service equipment was adequate.

#### 5. ELECTRIC ROOMS

a. Clearances: ☒ Good ☐ Requires Repair

Describe the Nature of Repairs:

No repairs required in the electrical rooms.

**6. GUTTERS, WIREWAYS, ETC.**

a. Location:

☒

Good

☐

Requires Repair

Describe the Nature of Repairs:

No repairs required.

b. Taps and Box Fill:

☒

Good

☐

Requires Repair

Describe the Nature of Repairs:

No repairs required.

**7. ELECTRICAL SWITCHGEAR**

a. Panel #

( (56) Tenant 125 Amp )

☒

Good

☐

Needs Repairs

b. Panel #

( House 125 Amp )

☒

Good

☐

Needs Repairs

c. Panel #

( Elevator 100 Amp Disconnect )

☒

Good

☐

Needs Repairs

d. Panel #

( (8) 400A Main )

☒

Good

☐

Needs Repairs

e. Panel #

( )

☐

Good

☐

Needs Repairs

Describe the Nature of Repairs:

No repairs required.

**8. BRANCH CIRCUITS**

a. Identified:

☒

Yes

☐

Must Be Identified

b. Conductors:

☒

Good

☐

Deteriorated

☐

Must Be Replaced

Describe the Nature of Repairs:

No repairs required.

**9. GROUNDING OF SERVICE**☒

Good

☐

Repairs Required

Comments:

The services were noted to be bonded to grounding rods.

**10. GROUNDING OF EQUIPMENT**☒

Good

☐

Repairs Required

Comments:

No repairs required.

**11. SERVICE CONDUITS/RACEWAYS**



Good



Repairs Required

Comments:

Service conduits and raceways were noted to be in good condition.

**12. SERVICE CONDUCTOR AND CABLES**



Good



Repairs Required

Comments:

Service conductors and cables were noted to be in good condition.

**13. GENERAL CONDUIT/RACEWAYS**



Good



Repairs Required

Comments:

General conduits and raceways were noted to be in good condition.

**14. FEEDER CONDUCTORS**

Good



Repairs Required

Comments:

Feeder conductors noted to be in good condition.

**15. BUSWAYS**

a. Location:



Good



Repairs Required

Describe the Nature of Repairs:

No repairs required.

**16. OTHER CONDUCTORS**

Good



Repairs Required

Comments:

N/A

**17. EMERGENCY LIGHTING**

Good



Repairs Required

Comments:

N/A



**18. BUILDING EGRESS ILLUMINATION**

Good



Repairs Required

Comments:

All egress Illumination inspected appears to be in serviceable condition.

**19. FIRE ALARM SYSTEM**

Good



Repairs Required

Comments:

Fire alarm system was noted to be in good condition.

**20. SMOKE DETECTORS**

Good



Repairs Required

Comments:

Hard wired or battery operated smoke detectors located in dwelling units.

**21. EXIT LIGHTS**

Good



Repairs Required

Comments:

All exit lights inspected appears to be in serviceable condition.

**22. EMERGENCY POWER SYSTEMS**☐

Good

☐

Repairs Required

Comments:

N/A

**23. WIRING AND CONDUIT AT ALL PARKING LOTS AND GARAGES**☒

Good

☐

Repairs Required

Comments:

Wiring and conduit at parking lots were noted to be in good condition.

**24. SWIMMING POOL WIRING**☐

Good

☐

Repairs Required

Comments:

N/A

**25. WIRING TO MECHANICAL EQUIPMENT**☒

Good

☐


Repairs Required

Comments:

All mechanical equipment wiring was noted to be in serviceable condition.

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



Building Elevation (North)



Building Elevation (South)

Property Consulting Group, Inc.



# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



Building Elevation (East)



Building Elevation (West)

Property Consulting Group, Inc.

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



2. Present Condition of Overall Structure



2.c. View of Surface Conditions

Property Consulting Group, Inc.

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



5. Building Foundation - Uniformity



7.a.1. Type & Condition of the Current Roof



# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



7.a.2. View of Air Conditioning Equipment/Other:



7.a.3. View of Roof Drains, Scuppers

Property Consulting Group, Inc.

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog




7.b.1. Type & Condition Floor System(s)



7.b.2. View of Balconies

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



7.b.3. View of Stairs & Landings



7.b.5. View of Guardrails & Handrails

Property Consulting Group, Inc.



# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



10.a. View of Windows




10.c.1. View of Exterior Doors

# Lyndhurst H Deerfield Beach, FL 33442

## Structural Photolog



11.d. View of Joints/Seams




11.f. View of Ventilation



# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



3. View of Electrical Services



4. View of Service Equipment



# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



5. View of Electrical Room



5. View of Electrical Room

# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



7. View of Electrical Switchgear



8. View of Electrical Panel

# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



9. View of Grounding of Service



11. View of Service Conductors/Raceways



# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



11. View of Service Conductors/Raceways



13. View of General Conduit/Raceways

# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



18. View of Building Egress Illumination



20. View of Smoke Detectors

# Lyndhurst H Deerfield Beach, FL 33442

## Electrical Photolog



20. View of Smoke Detectors



21. View of Exit Lights